

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2024

Submitted Date:

08/02/2024

Document Number:

707801052

**FIELD INSPECTION FORM**Loc ID 334457 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10639

Name of Operator: CPX PICEANCE HOLDINGS LLC

Address: 34 S WYNDEN DR STE 240

City: HOUSTON State: TX Zip: 77056

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Kurtenbach, Nick		nick@cpxpiceance.com	

**General Comment:****ECMC Inspection Report Summary**

On Thursday 8/1/2024, I, Inspector Scott Ramsey and Wayne Smelser, attempted to conduct routine inspection at CPX TPR 25A, at Location # 334457 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

We were unable to access location due to a locked gate that the supplied combo was not the correct one. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area.

I attempted to contact Nick Kurtenbach at 8:45 and left a message to inform him of us going to location. Upon arrival to locked gate and combo didn't work, I proceeded down to CPX central tank battery and called the two emergency numbers and had to leave a voicemail on both. We waited for an hour and no response from anyone. The next morning 8/2/24 at approximately 9 AM I received a voicemail from Nick stating he was traveling the day before but didn't know the new combo for the gate and was going to try to find out for us.

During this inspection the following compliance issues were observed:

1. No access to location (locked gate)
2. No immediate emergency contact response.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

1. No access to location (locked gate)  
2. No immediate emergency contact response. (713-554-9031) (720-233-8275) (970-987-2220) See inspector comment

Corrective Action: Provide key, combinations, or alternate method of access to comply with rule 204.

Date: 08/03/2024

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multilple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403875364	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649744">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649744</a>

Date Run: 8/9/2024 Doc [#707801052]

Page 2 of 2