

Inspection Photos

August 6th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326526

Inspection Document #: 714001059

La Plata County, CO

Township: SWNW 34 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huber 2-34
Location ID: 326526

8/6/24
+37.261578,-107.737667
226° SW



Photo 1. View of the location taken from the access point facing center.

Inspection Photos
Location Name: Huber 2-34
Location ID: 326526



Photo 2. Storm water corrective action identified in inspection doc #693903541 has been addressed/resolved.

Inspection Photos
Location Name: Huber 2-34
Location ID: 326526

8/6/24
+37.261434,-107.738253
292° W



Photo 3. View of flowering Musk thistle and patch of Mullein observed in the western portion of the disturbance.

Inspection Photos
Location Name: Huber 2-34
Location ID: 326526



Photo 4. Reference area comprised of Pine, Antelope bitterbrush and Crested wheatgrass.