

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 533-5 Pad

Location # 334779



Photo # 5333 From entrance to location



Photo # 5334 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 533-5 Pad

Location # 334779




Photo # 5335 Location



Photo # 5336 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 533-5 Pad

Location # 334779



Photo # 5337 Location



Photo # 5338 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 533-5 Pad

Location # 334779



Aug 8, 2024 at 9:17:47 AM
CO



Aug 8, 2024 at 9:22:50 AM
CO

Photo # 5339 Location

Photo # 5340 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC HARRIS RWF 533-5 Pad

Location # 334779



Photo # 5341 Battery sign weathered & cracking/starting to become illegible

