

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403838786

Date Received:
06/27/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

.

rbucogccinspectionreports@chevron.onmicrosoft.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900689

Inspection Date: 06/10/2024

FIR Submit Date: 06/17/2024

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 329434

Location Name: SMITH-64N64W Number: 9SWNW County: _____

Qtrqtr: SWN Sec: 9 Twp: 4N Range: 64W Meridian: 6
W

Latitude: 40.328686 Longitude: -104.562604

FACILITY - API Number: 05-123-00 Facility ID: 329434

Facility Name: SMITH-64N64W Number: 9SWNW

Qtrqtr: SWN Sec: 9 Twp: 4N Range: 64W Meridian: 6
W

Latitude: 40.328686 Longitude: -104.562604

CORRECTIVE ACTIONS:

1 CA# 195936

Corrective Action: Remove stained soil per Rule 912.a.

Date: 06/24/2024

Response: CA COMPLETED

Date of Completion: 06/24/2024

Operator Comment: FIRR DOC 403835323

ECMC Decision: _____

ECMC
Representative:

2 CA# 195937

Corrective Action: Operator shall comply with Rule 1002.e.(1) to minimize erosion, alteration of natural features, removal of surface materials, and degradation due to contamination. Operator shall reasonably minimize land disturbances and conduct Interim Reclamation per Rule 1003.

Date: 06/24/2024

Response: CA COMPLETED

Date of Completion: 06/25/2024

Operator
Comment:

Complied with Rule 1002

ECMC Decision:

ECMC
Representative:

3 CA# 195938

Corrective Action: Operator shall repair erosion and install stormwater BMP's along the perimeter of the location to control run-off and run-on per Rule 1002.f.

Date: 06/24/2024

Response: CA COMPLETED

Date of Completion: 06/24/2024

Operator
Comment:

End gun from pivot is watering site and causing erosion. We are working on a long term solution after crop season is completed.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Working with landowner and the inspector to get long term solution for issue once crop season is over.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed: _____

Title: HSE

Date: 6/27/2024 1:26:20 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------------|
| 403838786 | FIR RESOLUTION SUBMITTED |
| 403838803 | photo |

Total Attach: 2 Files