

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403886098

Date Received:

08/13/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 600 TRAVIS STREET SUITE 5050
City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Tyler Faldyn</u>	<u>832-748-1090</u>	<u>tfaldyn@americanhelium.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 696204915
Inspection Date: 05/08/2023 FIR Submit Date: 05/09/2023 FIR Status: _____

Inspected Operator Information:

Company Name: LOCIN OIL CORPORATION Company Number: 51130
Address: 600 TRAVIS ST STE 6161
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 322403

Location Name: FEDERAL-67S104W Number: 34NWNE County: _____
Qtrqtr: NWNE Sec: 34 Twp: 7S Range: 104W Meridian: 6
Latitude: 39.412954 Longitude: -108.974062

FACILITY - API Number: 05-045-00 Facility ID: 322403

Facility Name: FEDERAL-67S104W Number: 34NWNE
Qtrqtr: NWNE Sec: 34 Twp: 7S Range: 104W Meridian: 6
Latitude: 39.412954 Longitude: -108.974062

CORRECTIVE ACTIONS:

1 CA# 170707

Corrective Action: Install sign to comply with Rule 605.h. Date: 05/03/2023

Response: CA COMPLETED Date of Completion: 06/26/2023

Operator Comment: Locin responded to this corrective action on Document #696205061 on 06/26/2023. We are submitting this FIRR to close the record. Please see attached photo of signage.

ECMC Decision: _____

	ECMC Representative:		
--	----------------------	--	--

2	CA# 170708		
Corrective Action:		Comply with 1003.a	Date: 11/30/2022
Response:		CA COMPLETED	Date of Completion: 06/26/2023
Operator Comment:		Locin responded to this corrective action on Document #696205061 on 06/26/2023. We are submitting this FIRR to close the record.	
ECMC Decision: _____			
ECMC Representative:			

3	CA# 170709		
Corrective Action:		Comply with 1002.f: Install or repair required stormwater and erosion control BMPs at access road to properly manage runoff.	Date: 04/07/2023
Response:		CA COMPLETED	Date of Completion: 06/26/2023
Operator Comment:		Locin responded to this corrective action, as documented on the inspection Document #696205061 on 06/26/2023. We are submitting this FIRR to close the record.	
ECMC Decision: _____			
ECMC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	Locin is submitting this FIRR to correct and resolve the historic records.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Niah Wilson	Signed: _____
Title: Regulatory Specialist	Date: 8/13/2024 1:43:06 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403886109	Field Inspection Form Response
403888071	Federal 1-34 Signage Photo
403888073	Federal 1-34 Tank Label

Total Attach: 3 Files