

Phoenix  
Mary Hite Fee #1  
Location ID: 316742



Tank battery signage lacking information



Load out bucket over flowing and stained soils under it

Phoenix  
Mary Hite Fee #1  
Location ID: 316742



Weeds



Tank signage lacking information

Phoenix  
Mary Hite Fee #1  
Location ID: 316742



Weeds



Secondary containment behind tank down hill side

Phoenix  
Mary Hite Fee #1  
Location ID: 316742



Location



Location /weeds

Phoenix  
Mary Hite Fee #1  
Location ID: 316742



Debris / well head



Debris

Phoenix  
Mary Hite Fee #1  
Location ID: 316742



Well signage lacking information / weeds / broken equipment



Debris

Phoenix  
Mary Hite Fee #1  
Location ID: 316742



Broken equipment



Well has lock but is open

Phoenix  
Mary Hite Fee #1  
Location ID: 316742



Debris



Debris

Phoenix  
Mary Hite Fee #1  
Location ID: 316742



Weeds throughout location



Access road