

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/06/2024

Submitted Date:

08/12/2024

Document Number:

707801067

**FIELD INSPECTION FORM**Loc ID 316753 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 20165 NORTH 67TH AVENUE 122A

City: GLENDALE State: AZ Zip: 85308

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Eisenach, Jason	970-301-0499	jeisenach@phxresources.com	Designated agent
, COGCC		dnr_cogccengineering@state.co.us	engineering
Heffner, Taylor	303-219-3362	theffner@phxresources.com	Principal agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232634	WELL	SI	08/01/2021	OW	107-06048	BAIERL FEE 3	SI

**General Comment:****ECMC Inspection Report Summary**

On Tuesday 8/6/2024, I, Inspector Scott Ramsey attempted to conduct a routine inspection at Phoenix Baierl fee #3, at Location # 316753 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, Access to location had a locked gate. I walk into location. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. No access to location due to a locked gate
  2. All of location and access over grown with weeds
  3. Battery and well signage are lacking information
  4. Well is S/I since 8/2021 and no MIT is on file. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Battery signage are lacking information		
Corrective Action:	Provide proper signage	Date:	09/12/2024
Type	WELLHEAD		
Comment:	well signage are lacking information		
Corrective Action:	Provide proper signage	Date:	09/12/2024

**Emergency Contact Number:**

Comment:	(303) 219-3362 Line was disconnected		
Corrective Action:	Provide proper emergency contact	Date:	08/16/2024

**Good Housekeeping:**

Type	OTHER		
Comment:	Locked gate at entrance		
Corrective Action:	Provide access to location VIA combinations	Date:	08/16/2024
Type	WEEDS		
Comment:	All of location and access over grown with weeds		
Corrective Action:	Remove weeds through out location	Date:	08/23/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	full of weeds			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	232634	Type:	WELL	API Number:	107-06048	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: Well is S/I since 8/2021 and no MIT is on file. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.									
Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.									
Date: 09/23/2024									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801074	Photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6663960">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6663960</a>