

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403893262

Date Received:
08/19/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, Evergreen</u>		<u>cogcc.evergreen@enrllc.com</u>
<u>Geyer, Aaron</u>		<u>aaron.geyer@pxd.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713600394
Inspection Date: 11/14/2023 FIR Submit Date: 11/16/2023 FIR Status: _____

Inspected Operator Information:

Company Name: PIONEER NATURAL RESOURCES USA INC Company Number: 10084
Address: 5205 N O'CONNOR BLVD STE 200
City: IRVING State: TX Zip: 75039

LOCATION - Location ID: 309427

Location Name: SPHINX DEEP-631S67W Number: 36SENW County: LAS ANIMAS
Qtrqtr: SENW Sec: 36 Twp: 31S Range: 67W Meridian: 6
Latitude: 37.303350 Longitude: -104.839270

FACILITY - API Number: 05-071- -00 Facility ID: 294968

Facility Name: SPHINX DEEP Number: 22-36
Qtrqtr: SENW Sec: 36 Twp: 31S Range: 67W Meridian: 6
Latitude: 37.303350 Longitude: -104.839270

CORRECTIVE ACTIONS:

1 CA# 188300

Corrective Action: Comply with 1004 Rules. Date: 04/06/2012

Response: CA COMPLETED Date of Completion: 08/19/2024

Operator Comment: Recontour location and pad per rule 1004

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Dyke

Signed: _____

Title: Construction Technician

Date: 8/19/2024 11:52:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403893279	Recontour and seed location
403893281	Landowner consultation

Total Attach: 2 Files