

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2024

Submitted Date:

08/21/2024

Document Number:

713601339**FIELD INSPECTION FORM**Loc ID 321658 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96730Name of Operator: WILLIFORD ENERGY COMPANYAddress: 6060 AMERICAN PLAZA SUITE 760City: TULSA State: OK Zip: 74135**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
GROWNS LARRY		lgrowns@willifordenergy.com	
Storts, Doug		pds@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207697	WELL	PR	01/01/2023	GW	017-06632	RHOADES UNIT 5-7	RI
321658	LOCATION	AC			-	RHOADES 5-613S48W 32SENW	RI

General Comment:

This is a follow up inspection of the RHOADES Unit #5-7 wellsite.
 The corrective action of the previous inspection was not completed.
 See attached photos and additional details within this report

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	OTHER			
Comment:	There is unused parts, barrels, and oily rags on location hat must be removed.			
Corrective Action:	Comply with Rule 606			Date: 08/30/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Lube Oil				
Comment:	There are stained soils next to the pumpjack that must be cleaned up and properly disposed.			
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906.			Date: 09/10/2024
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
			Fail	Material Handling And Spill Prevention	Fail	

Comment: There are areas where stormwater is pooling and vehicles are driving around the impacted road causing unnecessary disturbance. The access road needs to be repaired and maintained with BMP's such as road base and culverts. The roads needs to be built up to allow stormwater drainage. Previous corrective action was not completed. There was a bucket full of oil that is close to spilling or fallin over.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)
Comply with 603.I.

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601340	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6673244