

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403884208

Date Received:

08/09/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10684

Name of Operator: EPIC ENERGY LLC

Address: 332 RD 3100

City: AZTEC State: NM Zip: 87410

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

John Thompson

505-327-4892

john@walsheng.net

Shawna Martinez

505-327-4892

Shawna@walsheng.net

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000896

Inspection Date: 06/25/2024

FIR Submit Date: 07/01/2024

FIR Status: _____

Inspected Operator Information:

Company Name: EPIC ENERGY LLC

Company Number: 10684

Address: 332 RD 3100

City: AZTEC State: NM Zip: 87410

LOCATION - Location ID: 325125

Location Name: MARTINEZ-N33N9W Number: 24SENW County: _____

Qtrqtr: SENW Sec: 24 Twp: 33N Range: 9W Meridian: N

Latitude: 37.092160 Longitude: -107.782310

FACILITY - API Number: 05-067- -00 Facility ID: 325125

Facility Name: MARTINEZ-N33N9W Number: 24SENW

Qtrqtr: SENW Sec: 24 Twp: 33N Range: 9W Meridian: N

Latitude: 37.092160 Longitude: -107.782310

CORRECTIVE ACTIONS:

1 ☒ CA# 196356

Corrective Action: Comply with rule 1003.f

Date: 07/15/2024

Response: CA COMPLETED

Date of Completion: 08/07/2024

Operator Comment: Cheatgrass and Russian thistle have been removed.

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.
----------------------	--

2 CA# 196357

Corrective Action:	Comply with rule 1002 Install or repair required BMPs.
--------------------	--

Date: 07/15/2024

Response: CA COMPLETED

Date of Completion: 08/15/2024

Operator	Rutting on the southeast corner of the active pad has been repaired.
Comment:	The surface owner of the access road is Southern Ute.

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

OPERATOR COMMENT AND SUBMITTAL	
1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
100	

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Shawna Martinez

Signed:

Title: Regulatory

Date: 8/9/2024 12:25:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403884208	FIR RESOLUTION SUBMITTED
403884328	Corrective Action Photos

Total Attach: 2 Files