

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-14 Pad
Location ID: 324214



Location Overview: Location is within High Priority/Density Habitat areas & in close proximity to Bald Eagle Roost Sites. Location is approximately 110 yards from a creek/drainage that contributes to the Colorado River.

Section/Township/Range: 14 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-14 Pad
Location ID: 324214



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-14 Pad
Location ID: 324214



Photo # 6451 Erosion & transport of sediment off location & into a vegetated area/failure to minimize erosion & transport of sediment



Photo # 6452 Erosion & transport of sediment off location & into a vegetated area/failure to minimize erosion & transport of sediment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-14 Pad
Location ID: 324214



Photo # 6453 Erosion & transport of sediment off location & into a vegetated area/failure to minimize erosion & transport of sediment



Photo # 6454 Erosion & transport of sediment off location & into a vegetated area/failure to minimize erosion & transport of sediment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-14 Pad
Location ID: 324214



Photo # 6455 Erosion & transport of sediment off location & into a vegetated area/failure to minimize erosion & transport of sediment



Photo # 6456 Erosion & transport of sediment off location & into a vegetated area/failure to minimize erosion & transport of sediment

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 34-14 Pad
Location ID: 324214



Aug 26, 2024 at 10:34:30 AM
CO

Photo # 6457 Erosion & transport of sediment off location & into a vegetated area/failure to minimize erosion & transport of sediment



Aug 26, 2024 at 10:34:58 AM
CO

Photo # 6458 Erosion & transport of sediment off location & into a vegetated area/failure to minimize erosion & transport of sediment