

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2024

Submitted Date:

08/29/2024

Document Number:

711901242**FIELD INSPECTION FORM**Loc ID 317148 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 10536

Name of Operator: SMITH ENERGY LLC

Address: 1540 MAIN ST SUITE 218 #334

City: WINDSOR State: CO Zip: 80550

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Chris		smithenergy@live.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236845	WELL	PR	02/01/2011	GW	121-09342	PRICE, JIM-CATTLE CO 1-7	PR

General Comment:[ROUTINE FIR - READ COMMENTS](#)

Location**Lease Road:**

Type	Access		
comment:	MAINTAIN LEASE ROAD		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type			
Comment:	REPLACE STICKER PER 600 SERIES RULES		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	REPLACE STICKER PER 600 SERIES RULES		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: NONE

☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 0		corrective date
Comment:	NO CHANGE		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	236845	Type:	WELL	API Number:	121-09342	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	GW								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

ECMC Comments		
Comment	User	Date
ROUTINE FIR - READ COMMENTS	schureky	08/29/2024