

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2024

Submitted Date:

08/26/2024

Document Number:

713400259**FIELD INSPECTION FORM**Loc ID 336045 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, CHEVRON		atlx@chevron.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Aaron Katz		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291500	WELL	TA	12/01/2017	GW	045-14406	SKR 598-35-AV-10	TA

General Comment:**CECMC Inspection Report Summary**

On 8/16/2024 at approximately 11:17, Compliance Inspector Dusty Popejoy conducted an on-site inspection to observe a plugging operation on SKR 598-35-AV-10 well API# 05-045-14406 Document #403889224 at CHEVRON USA INC SKR-65S98W/35NWNE at Location ID #336045 in Garfield County, Colorado. At this time no plugging operations were observed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Any Corrective Actions from previous Inspections are still applicable.

Location				
Lease Road:				
Type	Access			
comment:	Access.			
Corrective ActionL			Date:	
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	911/1-877-257-6007			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 291500 Type: WELL API Number: 045-14406 Status: TA Insp. Status: TA

CementCement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Please refer to document #'s 403889196 & 403889224

8/16/2024 at 11:17 hours arrived on location to observe scheduled plugging operations. At this time no rig or plugging equipment were on location, spoke to a Chevron lease operator on location, he called someone that was over plugging operations and informed me that well SKR 598-35-AV-10 was plugged back in May of 2024 and were waiting to cut casing and remove wellhead until they were completed with all plugging operations. Documents show plugging operations starting on 8/16/2024 at 07:00 hours Spoke with Chevron consultant Dallas Russell 8/19/2024 and he confirmed P&A date was 5/11/2024

Corrective Action: Contact engineering.

Date: 09/02/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403900461	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6681575
713400260	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6681561