

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2024

Submitted Date:

08/25/2024

Document Number:

695110170

**FIELD INSPECTION FORM**

Loc ID 322107 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10754  
Name of Operator: FOUR CORNERS ENERGY LLC  
Address: 500 DALLAS STREET #1650  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 8 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		JFulcher@bwenergyllaw.com	
,		rhankins@americanhelium.us	
Demarco, Jaime		jdemarco@blm.gov	
,		dnr_ecmc_engineering@state.co.us	
,		irobets@americanhelium.us	
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208980	WELL	SI	10/01/2017	GW	033-06085	WILLIE WASCHKE 4-17	SI

**General Comment:**

ECMC staff performed a field inspection on 08/25/2024.  
Issues were found requiring corrective action. See inspection text and photos for details.  
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	PHOTO 1: WELL SIGN/ COMPANY NAME POST ON LOCATION IS INACCURATE AND EMERGENCY CONTACT NUMBERS ARE INVALID.		
Corrective Action:	UPDATE EMERGENCY CONTACT PHONE NUMBER AS SOON AS POSSIBLE AND POST CURRENT OPERATOR NAME PER RULE 605.		Date: 10/26/2024
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	PHOTO 2, 4, 5 & 6: LOCATION/ WEED MAINTANANCE NEEDED THROUGHOUT THE LOCATION INSITER BURMS FOR TANK BATTERY AND HEATED SEPARATOR.		
Corrective Action:	MAINTAIN WEEDS THROUGHOUT LOCATION AND REMOVE ALL WEEDS INSIDE TANK BATTERY BURMS, Comply with Rule 603.f		Date: 09/05/2024
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Last cal. report was in July 2016		
Corrective Action:	PROVIDE AREA FIELD INSPECTOR (@ tom.beardslee@state.co.us & steve.labowskie@state.co.us) A COPY OF THE GAS METER CALIBRATION RECORD OR KEEP A COPY OF LAST CALIBRATION RECORD ON LOCATION.		Date: 09/05/2024
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		37.636579,-104.962545
Comment:		See photo of tank color/condition. Production facility is clearly visible from a public highway, road, or publicly-maintained trail. Facility paint is not uniform, non			
Corrective Action:		Comply with rukle 425. CA adjusted for seasonal conditriions, previous operator cited for same issue. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.			Date:
<b>Paint</b>					
Condition	Inadequate				
Other (Content)	FLIR CAMARA INDICATES FLUID LEVEL IS APPROX. 6'				
Other (Capacity)	400 BBL				
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:		SEE HOUSE KEEPING SECTION FOR CORRECTIVE ACTION ON WEEDS ON AND INSIDE BERMS			
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 208980 Type: WELL API Number: 033-06085 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** Well shut in 8/2016. No MIT on record.  
Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.  
Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

**Corrective Action:** Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208. This is the second notice for this corrective action, immediate action is required. **Date:** \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 12/12/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONE

End Surf Csg Pressure: 0

**Comment:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: weeds on row need maintained.

Corrective Action: maintain weeds on row per rule 606.

Date: 09/06/2024

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403902982	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684511">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684511</a>
695110184	INSP. PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684491">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6684491</a>