

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2024

Submitted Date:

09/03/2024

Document Number:

717700338**FIELD INSPECTION FORM**Loc ID 437847 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437847	LOCATION	AC			-	Anschutz Equus Farms 4-62-33 SWNW	AC

**General Comment:**[This is an audit on the Location](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Unmarked Riser, needs to be marked.		
Corrective Action:	Comply with the 1100 rules	Date:	12/31/2024
Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heater Treater	# 1		
Comment:	Line Heater		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Gaslift risers		
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:	Missing bird protector on line heater needs to be replaced.		
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.	Date:	12/31/2024

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	437847	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	Active location								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday, August 27, 2024, at approximately 9:37 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Location: Anschutz Equus Farms 4-62-33 SWNW Production Equipment Operator: Civitas Location ID # 437847 County: Weld</p> <p>During the inspection, a producing well was observed. The following possible compliance issues were identified:</p> <p>Unmarked Risers: Unmarked riser, needs to be marked. Comply with the 1100 rules</p> <p>Bird Protector: Missing bird protector on line heater needs to be replaced. Install sign to comply with Rule 605.h.</p> <p>A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.</p> <p>Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	09/03/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717700339	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691581">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691581</a>