

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403912453

Date Received:

09/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Parrish, Melissa

970-397-3896

mparrish@fundareresources.com

Smith, Sydney

303-910-4511

ssmith@fundareresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708200653

Inspection Date: 10/26/2023

FIR Submit Date: 10/31/2023

FIR Status: _____

Inspected Operator Information:

Company Name: FUNDARE RESOURCES OPERATING COMPANY LLC

Company Number: 10773

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

LOCATION - Location ID: 445579

Location Name: Horsetail Number: 30H Pad County: _____

Qtrqr: SENE Sec: 30 Twp: 10N Range: 57W Meridian: 6

Latitude: 40.810644 Longitude: -103.787250

FACILITY - API Number: 05-123- -00 Facility ID: 445579

Facility Name: Horsetail Number: 30H Pad

Qtrqr: SENE Sec: 30 Twp: 10N Range: 57W Meridian: 6

Latitude: 40.810644 Longitude: -103.787250

CORRECTIVE ACTIONS:

1 CA# 187459

Corrective Action: Comply with Rule 606. The location will remain out of compliance until the corrective action has been completed.

Date: 10/26/2023

Response: CA COMPLETED

Date of Completion: 01/15/2024

Jersey barriers are no longer being stored on location. These jersey barriers have been implemented around wellheads to create visible barrier putting site within compliance of Rule 606. - Please see attached photo

Operator Comment:	documentation.		
ECMC Decision:			
ECMC Representative:			

2	CA# 187460		
Corrective Action:		Comply with Rule 606. The location will remain out of compliance until the corrective action has been completed.	Date: <u>10/26/2023</u>
Response:		CA COMPLETED	Date of Completion: <u>01/15/2024</u>
Operator Comment:		All trash & debris including the flare foundation have been removed & properly disposed of from location in compliance with Rule 606. Please see attached photo documentation.	
ECMC Decision:			
ECMC Representative:			

3	CA# 187461		
Corrective Action:		Comply with Rule 1003. The locaiton will remain out of compliance until the corrective action has been resolved.	Date: <u>10/26/2023</u>
Response:		CA COMPLETED	Date of Completion: <u>09/06/2024</u>
Operator Comment:		Photos obtained during this inspection occurred during the dormant season. In compliance with Rule 1003, you can see in the provided photo documentation from the Vegetation Assessment performed by Marcom the Drill Pad Post Reclamation Vegetation has surpassed the reference area with native grass.	
ECMC Decision:			
ECMC Representative:			

OPERATOR COMMENT AND SUBMITTAL	
Comment:	
<p>I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.</p> <p>Print Name: <u>Melissa Parrish</u> Signed: _____</p> <p>Title: <u>Production Compliance Reg</u> Date: <u>9/6/2024 1:10:14 PM</u></p>	

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403912471	Horsetail 30 H Pad COGCC Corrective Actions Completed
403912472	Horsetail 30H - Vegetation Assessment Photo doc 9.4.2024

Total Attach: 2 Files