

OIL AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands. File in triplicate for State lands.

RECEIVED

DEC 20 1967

COLO. OIL & GAS CONSERVATION AND SERIAL NO.

Tidewater Pan-American

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL [X] GAS WELL [] OTHER [] We hope.
2. NAME OF OPERATOR Ed. F. Delaney
3. ADDRESS OF OPERATOR P.O. Box No. 734, Rangely, Colorado 81648
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1205 feet from west line of lot 5 east, 440 ft. North of center line of lot 5, Sec. 4.
14. PERMIT NO. 67-384
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5186 Gr.
7. UNIT AGREEMENT NAME None
8. FARM OR LEASE NAME Tidewater Pan American
9. WELL NO. 11-"A"
10. FIELD AND POOL, OR WILDCAT Rangely, Mancos
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 4 T1N, 102W, 6th.
12. COUNTY OR PARISH Rio Blanco
13. STATE Colo.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :

SUBSEQUENT REPORT OF :

TEST WATER SHUT-OFF []

PULL OR ALTER CASING []

WATER SHUT-OFF []

REPAIRING WELL []

FRACTURE TREAT []

MULTIPLE COMPLETE []

FRACTURE TREATMENT []

ALTERING CASING []

SHOOT OR ACIDIZE []

ABANDON []

SHOOTING OR ACIDIZING []

ABANDONMENT []

REPAIR WELL [X]

CHANGE PLANS []

(Other) []

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

At 2500 feet encountered nice blow of gas, from 2505-2508 feet more gas, 2510 - 2523 ft. oil recovered while drilling to surface in four minutes, this oil about 20 Bbls was followed by heavy rotary mud, this mud on laboratory test showed quebracho, sodium phosphate and baroid, no doubt coming from a deep well drilled in this area in the past to Weber.

We battled this mud inflow for five days, slow process, however, we were gaining and getting some oil showings and new gas, the complete clearing of this situation, if ever, will take a month or more so we will continue the battle in the spring when the weather is more comfortable.

springtime

Well presently shut in, "awaiting ~~operations~~ in the Rockies"

Table with 2 columns and 5 rows: DVR, FJP, HMM, JAM, JJD. Checkmarks are present in the second column for FJP, HMM, JAM, and JJD.

18. I hereby certify that the foregoing is true and correct

SIGNED

Ed. Delaney

TITLE Operator

DATE 12/18/67

(This space for Federal or State office use)

APPROVED BY

W. Rogers

TITLE Director

DATE

DEC 27 1967

CONDITIONS OF APPROVAL, IF ANY:



00039267