



FORM
INSP

Rev
X/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/23/2024
Submitted Date:
09/03/2024
Document Number:
714001145

Loc ID
326611

Inspector Name:
Mcdonough, Corey

On-Site Inspection ☐
2A Doc Num:

Operator Information:
ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:
☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:
5 Number of Comments
1 Number of Corrective Actions
☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258939	WELL	PR	04/13/2001	CBM	067-08393	MILLER FEDERAL 2	RI

General Comment:
On 8/23/2024 Reclamation Specialist Corey McDonough conducted a Reclamation and Stormwater Inspection at Simcoe LLC's Producing Miller Federal 2 Location in La Plata County, Colorado. This is a follow up inspection to inspection doc 693902883. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

During the inspection the following compliance issues were observed
- Interim Vegetation

Refer to the "Interim reclamation" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Date Run: 9/10/2024 Doc [#714001145]

Page 1 of 5

Inspected Facilities									
Facility ID:	258939	Type:	WELL	API Number:	067-08393	Status:	PR	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: [See weeds section of report.](#)

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Large patch of field bindweed observed flowering in the northern interim reclamation area.

Musk thistle, Canadian thistle and Mullein infestation appears to be controlled at this time with wilted and recently herbicide treated weeds observed around the location. However, minimal desirable vegetation observed around the location. Continue to manage and implement methods to establish desirable vegetation in interim reclamation areas.

Corrective Action Comply with rule 1003.f, treat/remove weeds. Spot seeding needs to be conducted within portions of the interim reclamation areas where desirable vegetation is struggling to establish.

Date **09/17/2024**

Overall Interim Reclamation **Fail**

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

At the time of the inspection, no storm water erosion issues were observed. Continue monitoring and managing storm water and erosion controls to ensure compliance with storm water regulations.

Corrective Action:

Date:

Pits:

☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403908702	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692061
714001151	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6692055