

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2024

Submitted Date:

09/03/2024

Document Number:

717700288

FIELD INSPECTION FORM

Loc ID 447050 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447048	WELL	PR	03/01/2023	OW	123-43462	Anschutz Equus Farms 3-62-4-0916B2	PR

General Comment:[This is an audit on the well](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well name sign at the well doesn't reflect what is in the ECMC data base. Submit proper documentation and correct designated well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	12/31/2024

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 447048

Type: WELL

API Number: 123-43462

Status: PR

Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/31/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
<div>ECMC Inspection Report Summary</div> <div>On Tuesday, August27, 2024, at approximately 9:10 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</div> <div>Well: Anschutz Equus Farms 3-62-4-0916B2</div> <div>Operator: Civitas</div> <div>API: 05-123-43462</div> <div>County: Weld</div> <div>During the inspection, a producing well was observed. The following possible compliance issues were identified:</div> <div>Incorrect Well Name: Well name sign at the well doesn't reflect what is in the ECMC data base. Submit proper documentation and correct designated well sign. Install sign to comply with Rule 605.d.</div> <div>A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.</div> <div>Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</div>	burnsa	09/03/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403907760	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691134
717700289	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691130