

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/03/2024

Submitted Date:

09/03/2024

Document Number:

717700338**FIELD INSPECTION FORM**Loc ID 437847 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437847	LOCATION	AC			-	Anschutz Equus Farms 4-62-33 SWNW	AC

General Comment:[This is an audit on the Location](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Location		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Unmarked Riser, needs to be marked.		
Corrective Action:	Comply with the 1100 rules	Date:	12/31/2024

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	#		
Comment:	Gaslift risers		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:	Missing bird protector on line heater needs to be replaced.		
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.	Date:	12/31/2024
Type: Horizontal Heater Treater	# 1		
Comment:	Line Heater		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	437847	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	Active location								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday, August27, 2024, at approximately 9:37 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Location: Anschutz Equus Farms 4-62-33 SWNW Production Equipment Operator: Civitas Location ID # 437847 County: Weld</p> <p>During the inspection, a producing well was observed. The following possible compliance issues were identified: Unmarked Risers: Unmarked riser, needs to be marked. Comply with the 1100 rules Bird Protector: Missing bird protector on line heater needs to be replaced. Install sign to comply with Rule 605.h. A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	09/03/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403908190	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691582
717700339	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6691581