

FORM 6 <small>Rev 11/20</small>	State of Colorado Energy & Carbon Management Commission <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>				<table border="1" style="width:100%; border-collapse: collapse;"><tr><td style="width:12.5%; text-align: center;">DE</td><td style="width:12.5%; text-align: center;">ET</td><td style="width:12.5%; text-align: center;">OE</td><td style="width:12.5%; text-align: center;">ES</td></tr></table>				DE	ET	OE	ES																																									
	DE	ET	OE	ES																																																	
	WELL ABANDONMENT REPORT				Document Number: 403915160 Date Received: 																																																
<p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.</p> <p>A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p>																																																					
<table style="width:100%;"><tr><td colspan="3">ECMC Operator Number: 100322</td><td colspan="3">Contact Name: Spencer Riebschlager</td></tr><tr><td colspan="3">Name of Operator: NOBLE ENERGY INC</td><td colspan="3">Phone: (346) 267-5252</td></tr><tr><td colspan="3">Address: 1099 18TH STREET SUITE 1500</td><td colspan="3">Fax:</td></tr><tr><td>City: DENVER</td><td>State: CO</td><td>Zip: 80202</td><td colspan="3">Email: drill@chevron.com</td></tr><tr><td colspan="3">For "Intent" 24 hour notice required,</td><td colspan="3">Name: Serna, Abe</td></tr><tr><td colspan="3"></td><td colspan="3">Tel: (720) 661-7317</td></tr><tr><td colspan="3">ECMC contact:</td><td colspan="3">Email: abe.serna@state.co.us</td></tr></table>						ECMC Operator Number: 100322			Contact Name: Spencer Riebschlager			Name of Operator: NOBLE ENERGY INC			Phone: (346) 267-5252			Address: 1099 18TH STREET SUITE 1500			Fax:			City: DENVER	State: CO	Zip: 80202	Email: drill@chevron.com			For "Intent" 24 hour notice required,			Name: Serna, Abe						Tel: (720) 661-7317			ECMC contact:			Email: abe.serna@state.co.us								
ECMC Operator Number: 100322			Contact Name: Spencer Riebschlager																																																		
Name of Operator: NOBLE ENERGY INC			Phone: (346) 267-5252																																																		
Address: 1099 18TH STREET SUITE 1500			Fax:																																																		
City: DENVER	State: CO	Zip: 80202	Email: drill@chevron.com																																																		
For "Intent" 24 hour notice required,			Name: Serna, Abe																																																		
			Tel: (720) 661-7317																																																		
ECMC contact:			Email: abe.serna@state.co.us																																																		
Type of Well Abandonment Report: <input checked="" type="checkbox"/> Notice of Intent to Abandon <input type="checkbox"/> Subsequent Report of Abandonment																																																					
<table style="width:100%;"><tr><td colspan="2">API Number 05-123-26395-00</td><td colspan="4">Well Number: 36-41</td></tr><tr><td colspan="2">Well Name: KARLBERG STATE</td><td colspan="4"></td></tr><tr><td>Location: QtrQtr: NESE</td><td>Section: 36</td><td>Township: 7N</td><td>Range: 65W</td><td colspan="2">Meridian: 6</td></tr><tr><td colspan="2">County: WELD</td><td colspan="4">Federal, Indian or State Lease Number: ST 81-6538</td></tr><tr><td colspan="2">Field Name: EATON</td><td colspan="4">Field Number: 19350</td></tr></table>						API Number 05-123-26395-00		Well Number: 36-41				Well Name: KARLBERG STATE						Location: QtrQtr: NESE	Section: 36	Township: 7N	Range: 65W	Meridian: 6		County: WELD		Federal, Indian or State Lease Number: ST 81-6538				Field Name: EATON		Field Number: 19350																					
API Number 05-123-26395-00		Well Number: 36-41																																																			
Well Name: KARLBERG STATE																																																					
Location: QtrQtr: NESE	Section: 36	Township: 7N	Range: 65W	Meridian: 6																																																	
County: WELD		Federal, Indian or State Lease Number: ST 81-6538																																																			
Field Name: EATON		Field Number: 19350																																																			
<i>Only Complete the Following Background Information for Intent to Abandon</i>																																																					
<table style="width:100%;"><tr><td colspan="2">Latitude: 40.528170</td><td colspan="4">Longitude: -104.604320</td></tr><tr><td>GPS Data: GPS Quality Value: 3.0</td><td>Type of GPS Quality Value: PDOP</td><td colspan="4">Date of Measurement: 02/21/2008</td></tr><tr><td colspan="6">Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems</td></tr><tr><td colspan="6"><input type="checkbox"/> Other</td></tr><tr><td colspan="2">Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</td><td colspan="4">Estimated Depth:</td></tr><tr><td colspan="2">Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</td><td colspan="4">If yes, explain details below</td></tr><tr><td colspan="2">Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</td><td colspan="4">If yes, explain details below</td></tr><tr><td colspan="6">Details: </td></tr></table>						Latitude: 40.528170		Longitude: -104.604320				GPS Data: GPS Quality Value: 3.0	Type of GPS Quality Value: PDOP	Date of Measurement: 02/21/2008				Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems						<input type="checkbox"/> Other						Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Estimated Depth:				Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below				Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below				Details:					
Latitude: 40.528170		Longitude: -104.604320																																																			
GPS Data: GPS Quality Value: 3.0	Type of GPS Quality Value: PDOP	Date of Measurement: 02/21/2008																																																			
Reason for Abandonment: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																																																					
<input type="checkbox"/> Other																																																					
Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Estimated Depth:																																																			
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below																																																			
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If yes, explain details below																																																			
Details:																																																					
Current and Previously Abandoned Zones																																																					
<table style="width:100%;"><tr><th>Formation</th><th>Perf. Top</th><th>Perf. Btm</th><th>Abandoned Date</th><th>Method of Isolation</th><th>Plug Depth</th></tr><tr><td>CODELL</td><td>7136</td><td>7150</td><td></td><td></td><td></td></tr></table> <p>Total: 1 zone(s)</p>						Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth	CODELL	7136	7150																																							
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																																																
CODELL	7136	7150																																																			
Casing History																																																					
<table style="width:100%;"><tr><th>Casing Type</th><th>Size of Hole</th><th>Size of Casing</th><th>Grade</th><th>Wt/Ft</th><th>Csg/Liner Top</th><th>Setting Depth</th><th>Sacks Cmt</th><th>Cmt Btm</th><th>Cmt Top</th><th>Status</th></tr><tr><td>SURF</td><td>12+1/4</td><td>8+5/8</td><td>NA</td><td>24</td><td>0</td><td>647</td><td>230</td><td>647</td><td>0</td><td>VISU</td></tr><tr><td>1ST</td><td>7+7/8</td><td>4+1/2</td><td>M80</td><td>11.6</td><td>0</td><td>7299</td><td>975</td><td>7299</td><td>0</td><td>CBL</td></tr></table>						Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status	SURF	12+1/4	8+5/8	NA	24	0	647	230	647	0	VISU	1ST	7+7/8	4+1/2	M80	11.6	0	7299	975	7299	0	CBL															
Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status																																											
SURF	12+1/4	8+5/8	NA	24	0	647	230	647	0	VISU																																											
1ST	7+7/8	4+1/2	M80	11.6	0	7299	975	7299	0	CBL																																											

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7086 with 2 sacks cmt on top. CIBP #2: Depth 6785 with 2 sacks cmt on top.
CIBP #3: Depth 3710 with 2 sacks cmt on top. CIBP #4: Depth 2605 with 10 sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 65 sks cmt from 847 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☒

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: _____ Cut and Cap Date: _____ Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____

*Wireline Contractor: _____

*Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

This well is part of the AOC (Order 1V-668) Alt MIT program.

3rd party wildlife surveys will be conducted on this well prior to rigging up for P&A activities.

Notification will be given to any adjacent building unit occupants within a 1000 feet of the wellhead of planned P&A start date.

Please be aware that Form 6 Approval can predate actual rig work by up to several months and that environmental conditions can change quickly over that time. Chevron's Environmental Site Screening Process incorporates full environmental field clearances within 7 days of a scheduled well-work activity once the well is added to the active workover rig schedule. Should sensitive HPH conditions be identified during the screening process, Chevron will delay the work until conditions (nesting) clear and/or consult directly with CPW for guidance and discussion of potential mitigation measures that may be incorporated.

CPW consult not required.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Sharon Strum

Title: Lead Wells Technical Asst

Date: _____

Email: sharon.strum@chevron.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

Expiration Date: _____

<u>COA Type</u>	<u>Description</u>
0 COA	

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
403915306	WELLBORE DIAGRAM
403915309	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)