

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-19 Pad
Location ID: 335396



**Location Overview: Location is within High Priority/Density
Habitat areas.**

Section/Township/Range: 19 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-19 Pad
Location ID: 335396



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-19 Pad
Location ID: 335396



Photo # 7797 Large amount of sediment building up at waddles on slopes around tank battery/may need maintenance in near future



Photo # 7798 Large amount of sediment building up at waddles on slopes around tank battery/may need maintenance in near future