

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2024

Submitted Date:

09/13/2024

Document Number:

713601432

**FIELD INSPECTION FORM**

Loc ID 308840 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283193	WELL	PR	09/08/2007	CBM	071-08708	BEIL 33-7 Tr	RI

**General Comment:**

This is a follow up reclamation inspection at the BEIL #33-7 Tr wellsite.  
See comments for maintenance issues that need to be addressed.

**Location**

**Lease Road:**

Type Access

comment:

Corrective ActionL

Date:

Overall Good:

**Signs/Marker:**

Type WELLHEAD

Comment:

Corrective Action:

Date:

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
		Adequate		
Comment	The material from the onsite pit has been removed.			
Corrective Action			Date:	

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is a culvert filled in with sediment and erosion on the road near the location. The disturbance area next to the pit will need to be reseeded this fall. Install or repair required BMPs per Rule 1002.f.(2)C

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601433	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705885">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6705885</a>