

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403873723

Date Received:

08/01/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 6 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 684901444

Inspection Date: 06/08/2016

FIR Submit Date: 06/08/2016

FIR Status: ACTION REQUIRED

Inspected Operator Information:

Company Name: EOG RESOURCES INC

Company Number: 27742

Address: 600 17TH ST STE 1100N

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 416280

Location Name: Randall Creek Number: 30 SESE County: _____

Qtrqtr: SESE Sec: 30 Twp: 12N Range: 62W Meridian: 6

Latitude: 40.974719 Longitude: -104.355186

FACILITY - API Number: 05-123- -00 Facility ID: 416280

Facility Name: Randall Creek Number: 30 SESE

Qtrqtr: SESE Sec: 30 Twp: 12N Range: 62W Meridian: 6

Latitude: 40.974719 Longitude: -104.355186

CORRECTIVE ACTIONS:

1 CA# 50383

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 07/08/2016

Response: CA COMPLETED

Date of Completion: 07/26/2024

Operator Comment: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.

ECMC Decision: _____

ECMC
Representative:

2 CA# 50384

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 07/08/2016

Response: CA COMPLETED

Date of Completion: 07/26/2024

Operator Comment: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.

ECMC Decision:

ECMC
Representative:

3 CA# 50385

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 07/08/2016

Response: CA COMPLETED

Date of Completion: 07/26/2024

Operator Comment: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.

ECMC Decision:

ECMC
Representative:

5 CA# 50387

Corrective Action: Mark all deadmen

Date: 06/23/2016

Response: CA COMPLETED

Date of Completion: 07/26/2024

Operator Comment: Operator has appropriately installed a marker for the identified deadman.

ECMC Decision:

ECMC
Representative:

6 CA# 50388

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 07/08/2016

Response: CA COMPLETED

Date of Completion: 07/26/2024

Operator Comment: Operator has provided follow-up to show that location complies with Rule 1002.f.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 8/1/2024 11:24:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403873723	FIR RESOLUTION SUBMITTED
403873889	Inspection Report Resolution

Total Attach: 2 Files