

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403915024

Date Received:

09/17/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10814

Name of Operator: MDS ENERGY DEVELOPMENT LLC

Address: 409 BUTLER RD SUITE A

City: KITTANNING State: PA Zip: 16201

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Kelsi Welch

kelsi.welch@iptwell.com

Jim Jacobsen

jim.jacobsen@iptwell.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708201524

Inspection Date: 08/19/2024

FIR Submit Date: 08/21/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: MDS ENERGY DEVELOPMENT LLC

Company Number: 10814

Address: 409 BUTLER RD SUITE A

City: KITTANNING State: PA Zip: 16201

#### LOCATION - Location ID: 471039

Location Name: Castor 7-59 Number: 10 County: \_\_\_\_\_

Qtrqtr: SWSE Sec: 10 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.583600 Longitude: -103.963208

#### FACILITY - API Number: 05-123-00 Facility ID: 471039

Facility Name: Castor 7-59 Number: 10

Qtrqtr: SWSE Sec: 10 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.583600 Longitude: -103.963208

### CORRECTIVE ACTIONS:

1 CA# 197883

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b.

Date: 08/31/2024

Response: CA COMPLETED

Date of Completion: 08/19/2024

Operator  
Comment:

Rathole was filled with gravel after removal & remediation of oily waste.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 197884

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e.

Date: 08/18/2024

Response: CA COMPLETED

Date of Completion: 08/18/2024

Operator  
Comment: Oily waste was removed & disposed of in accordance with Rule 905.e.

ECMC Decision:

ECMC  
Representative:

3 CA# 197885

Corrective Action: Operator shall immediately ensure operations are safe and will properly install safety controls and/or backfill the observed hole/subsidence pursuant to Rule 602.c.

Date: 08/22/2024

Response: CA COMPLETED

Date of Completion: 08/22/2024

Operator  
Comment: Subsidence has been backfilled pursuant to Rule 602.c.

ECMC Decision:

ECMC  
Representative:

4 CA# 197886

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e.

Date: 08/23/2024

Response: CA COMPLETED

Date of Completion: 08/21/2023

Operator  
Comment: Oily waste at loadout lines and compressor skid has been properly cleaned up and disposed of in accordance with Rule 905.e.

ECMC Decision:

ECMC  
Representative:

5 CA# 197887

Corrective Action: Comply with Rule 1002.f.(2)B to implement or modify BMPs for improved material handling and spill prevention.

Date: 08/23/2024

Response: CA COMPLETED

Date of Completion: 08/21/2024

Operator  
Comment: 5 gallon bucket outside of containment has been removed.

ECMC Decision:

ECMC  
Representative:

6 CA# 197888

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 08/23/2024

Response: CA COMPLETED

Date of Completion: 08/23/2024

Operator  
Comment:

Repair & installation of stormwater controls has commenced as part of interim reclamation of pad.

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelsi Welch

Signed:

Title: Permitting & Compliance

Date: 9/17/2024 10:53:54 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

--	--

Total Attach: 0 Files