

## DAILY DRILLING REPORT

Headbill 391

TULSA, OKLAHOMA

Note—Report all defects in machinery, casing, slope tests and injuries under Remarks

Diamond Back Drlg.

DATE Sept. 24 - 25 - 75

RECEIVED

JUL 12 1976

COMPANY

Delaney Pet.

WELL NO.

25

LEASE

Brick

STATE

colo.

SECTION

TWP. OR BLOCK

RNG. OR SURVEY

COUNTY

Rio Blanco

GOLD, OIL &amp; GAS CONS. COMM.

TOUR	FROM	TO	FORMATION	EMPLOYEE	OCCU-PATION	REG.	O.T.	RATE
1	2567		Shale	24 W.R. Burgett Darrell Torsell Carl Akin	DRLR DKM MM HLP HLP	8 14 8		
HRS. RUN	HRS. LOST	REASON	BITS RUN	HOURS RUN	CORE NO. & DESCRIPTION			
DEFLECTION								
CONE NOS.	SET NO.			CORE HEAD NO.				



00043507

REMARKS

4 hrs Working on Drlg. Engine  
Took Heat Exchanger to Vernal  
for Repairs

TOUR	FROM	TO	FORMATION	EMPLOYEE	OCCU-PATION	REG.	O.T.	RATE
2	2567	2770	Shale 2770 ft. D.L. Hit some water much oil @ 2750	25 W.R. Burgett Darrell Torsell Carl Akin	DRLR DKM MM HLP HLP	9 9 9		
HRS. RUN	HRS. LOST	REASON	BITS RUN	HOURS RUN	CORE NO. & DESCRIPTION			
DEFLECTION								
CONE NOS.	SET NO.			CORE HEAD NO.				

REMARKS

6 hrs. Drlg.  
3 hrs. Laying Down D.P.

TOUR	FROM	TO	FORMATION	EMPLOYEE	OCCU-PATION	REG.	O.T.	RATE
3					DRLR DKM MM HLP HLP			
HRS. RUN	HRS. LOST	REASON	BITS RUN	HOURS RUN	CORE NO. & DESCRIPTION			
DEFLECTION								
CONE NOS.	SET NO.			CORE HEAD NO.				

REMARKS

APPROVED BY FIELD SUPERINTENDENT