



99999999

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

C-034894

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

Government

9. WELL NO.

#3-1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3-T1N-R102W

12. COUNTY OR PARISH 13. STATE

Rio Blanco

CO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

JAN 22 1986

2. NAME OF OPERATOR

NORTHERN PUMP COMPANY

COLO. OIL & GAS CONS. COMM.

3. ADDRESS OF OPERATOR

1010 Hudson's Bay Centre, 1600 Stout Street
Denver, Colorado 80202-31304. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

350' FSL and 600' FEL

SESE

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5273' Gr

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☒
☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

RTD 6455' KB; 544.29' N.85°W

The Government #3-1 Well was plugged and abandoned as a dry hole, as follows:

6000-6455'	135 sx Class H
4475-4625'	67 sx Class H, 35% SS-4, 1% CaCl
3600-3750'	67 sx Class H, 35% SS-4, 1% CaCl
600-700'	45 sx Class H, 35% SS-4, 1% CaCl
0-40'	20 sx Class H, 35% SS-4, 1% CaCl

Cut off casing 4' below ground level and capped with a weld-on plate. Job complete
5:00 a.m. 1-12-86. Verbal approval given by Hank Szymanski of the Meeker, Colorado,
BLM Office and the Colorado Oil & Gas Conservation Commission.Mud weight above, below and between cement plug was 9.3 ppg. Cement plugs were spotted
in open-hole by The Western Company of North America. No casing was pulled.

Formation Tops:	Frontier	3403' KB
	Dakota	3650' KB
	Morrison	3764' KB
	Entrada	4472' KB
	Navajo	4706' KB
	Weber	6099' KB

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Manager

DATE 1-15-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DIRECTOR

DATE

CONDITIONS OF APPROVAL, IF ANY:

WRS	
FJP	
HHN	
JAM	
ROC	
LAR	
CGM	
ED	

*See In



00039036