



01072537

DATE

8-18-93

PAGE NO.

1

JOB LOG FORM 2013 R-3

CUSTOMER		WELL NO.		LEASE		JOB TYPE		TICKET NO.	
Chevron		40		Gentry		P: A		46760	
CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATION AND MATERIALS	
				T	C	TUBING	CASING		
	07:00							ON LOC R.3 up.	
	07:30							wait on pump TRK	
	09:00							Rig up pump tr/c	
	09:30							test lines	
	09:35							RIH tag 15'	
	09:38							start pump 1/2 BBL	
	09:44							shut down pump 100'	
	10:10							tag 1829' start pump try to	
								jet through. could not. Had	
								mixed cmnt Dumped to pit	
								POOH	
	10:48							on surface rig up Dr. 11' bit	
	11:28							RIH	
	11:58							tag start Dr. 11 18:30' Dr. 11	
								10' RIH	
	12:43							3600' No tags 1840' to 3600'	
								POOH	
	13:20							OOH Rig down tools T	
	13:40							RIH	
	14:20							@ 3600' Fresh water Flush	
								mix cmnt	
	14:28							cmnt in tag	
	14:38							start 5 BBL Fresh Flush	
	14:40							on Brine	
	14:54							start laying in plug to 3340'	
								to 3307'	
	15:04							poolh Displacing well w/Brine	
	16:26							start cmnt down tag	
	16:51							Lay in plug from 350' to 2400'	
								out of cmnt	
								Flush w/ 10 BBL Fresh	
	17:06							on surf Rig down For DAY	
	18:00							OFF LOC	

CUSTOMER