

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2024

Submitted Date:

09/14/2024

Document Number:

715500660

FIELD INSPECTION FORMLoc ID 312890 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kirkwood, Tom	(307) 577-5328	tomk@kirkwoodcompanies.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Hussman, Mark	(307) 277-3333	markh@kirkwoodcompanies.com	
Weinert, Dave	(307) 577-5329	davew@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222759	WELL	PR	05/01/2024	OW	081-06119	GOV'T-TRELEAVEN 9	PR

General Comment:**ECMC Inspection Report Summary**

On Thursday, 09/12/2024, Inspector Kirby Burchett, conducted a follow up field inspection at Wesco Operating Inc on the Gov't-Treleaven 9 well, Location #312890, in Moffat County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District and Black Bear area with High Priority and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715500539 on 8/8/24. FIRR #403900848 submitted by operator stating 4 of 4 Corrective Actions have been addressed. The following Corrective Action is unresolved and original due date remains:

1. Stained soil.

Refer to Inspection Photos for observed compliance issues.

While there during normal operations no additional compliance issues were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 866-965-6296

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	WELLHEAD			
Comment:	Stained soil between pumping unit and wellhead			
Corrective Action:	Remove and properly dispose of any stained and impacted soil to an approved facility.			Date: 08/24/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Manufacturer		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Corral panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment:	Chemical tanks on containments		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected Facilities									
Facility ID:	222759	Type:	WELL	API Number:	081-06119	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	July 2024 Production Report								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
				Material Handling And Spill Prevention		
Ditches						
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403921222	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6707239
715500661	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6707234