

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403920674

Date Received:  
09/13/2024

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10671  
Name of Operator: EDGE ENERGY II LLC  
Address: 600 12TH STREET SUITE 115  
City: GOLDEN State: CO Zip: 80401

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Turner, Ben</u>		<u>bturner@edgeenergy1.com</u>
<u>Kelsi Welch</u>		<u>Kelsi.welch@iptwell.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 679603454  
Inspection Date: 11/09/2020 FIR Submit Date: 11/09/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: EDGE ENERGY II LLC Company Number: 10671  
Address: 1301 WASHINGTON AVE SUITE 300  
City: GOLDEN State: CO Zip: 80401-6138

LOCATION - Location ID: 457767

Location Name: Simpson Number: 26 Pad County: \_\_\_\_\_  
Qtrqr: NESE Sec: 26 Twp: 8N Range: 66W Meridian: 6  
Latitude: 40.632960 Longitude: -104.735970

FACILITY - API Number: 05-123-00 Facility ID: 457767

Facility Name: Simpson Number: 26 Pad  
Qtrqr: NESE Sec: 26 Twp: 8N Range: 66W Meridian: 6  
Latitude: 40.632960 Longitude: -104.735970

CORRECTIVE ACTIONS:

1  CA# 144626

Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 603.h.(2)C. Refer to the 603.h guidance document for further details. Date: 02/09/2021

Response: CA COMPLETED Date of Completion: 02/09/2021

Operator Comment: CA was completed. Please reference follow up inspection doc #679603768 for confirmation of completed CA.

ECMC Decision: Approved via an AMI

ECMC Representative:

[Empty text box for ECMC Representative]

**2**  CA# 144627

Corrective Action: Install sign to comply with Rule 210.d.

Date: 12/09/2020

Response: CA COMPLETED

Date of Completion: 12/09/2020

Operator Comment:

CA was completed. Please reference follow up inspection doc #679603768 for confirmation of completed CA.

ECMC Decision: Approved via an AMI

ECMC Representative:

[Empty text box for ECMC Representative]

**3**  CA# 144628

Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.

Date: 02/09/2021

Response: CA COMPLETED

Date of Completion: 02/09/2021

Operator Comment:

CA was completed. Please reference follow up inspection doc #679603768 for confirmation of completed CA.

ECMC Decision: Approved via an AMI

ECMC Representative:

[Empty text box for ECMC Representative]

**OPERATOR COMMENT AND SUBMITTAL**

Comment: This is a retroactive submission to formally resolve the subject inspection and for compliance with Rule 210.b.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelsi Welch

Signed: \_\_\_\_\_

Title: Permitting & Compliance

Date: 9/13/2024 1:50:13 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403920674	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files