

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403886155

Date Received:
08/12/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____
Phone: () Fax: ()
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Luke Kelly	970-939-6353	lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900719
Inspection Date: 06/25/2024 FIR Submit Date: 06/28/2024 FIR Status: _____

Inspected Operator Information:

Company Name: EXTRACTION OIL & GAS INC Company Number: 10459
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 327754

Location Name: HIPPEN-61N68W Number: 32NWSW County: _____
Qtrqtr: NWS Sec: 32 Twp: 1N Range: 68W Meridian: 6
W
Latitude: 40.004840 Longitude: -105.033310

FACILITY - API Number: 05-123- -00 Facility ID: 327754

Facility Name: HIPPEN-61N68W Number: 32NWSW
Qtrqtr: NWS Sec: 32 Twp: 1N Range: 68W Meridian: 6
W
Latitude: 40.004840 Longitude: -105.033310

CORRECTIVE ACTIONS:

1 CA# 196272

Corrective Action: Manage noxious weeds at the well location. Date: 07/05/2024

Response: CA COMPLETED Date of Completion: 08/08/2024

Operator Comment: Operator has addressed the weeds and undesirable vegetation and mowed around this location in order to comply with Rule 606.

ECMC Decision: _____

ECMC
Representative:

2 CA# 196273

Corrective Action: Comply with the reclamation rules to remove all debris, abandoned gathering line risers, and flowline risers, and equipment (regardless of ownership) within three months of plugging (11/05/2019) the associated facility. All work should have been conducted by 02/05/2020.

Date: 07/28/2024

Response: CA COMPLETED

Date of Completion: 08/08/2024

Operator
Comment:

Operator has appropriately addressed and removed identified cement debris in order to comply with Rule 606.

ECMC Decision:

ECMC
Representative:

3 CA# 196274

Corrective Action: Comply with Rule 1105.f.(2). Form 44 should have been submitted within 90-days of completing abandonment.

Date: 07/28/2024

Response: CA COMPLETED

Date of Completion: 01/29/2020

Operator
Comment:

Operator has addressed the flowline abandonment with the following documents to comply with Rule 1105.f.(2).
Post AB Doc # 402298014

ECMC Decision:

ECMC
Representative:

4 CA# 196275

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: _____

There is no corrective action date due to this being out of compliance. Final reclamation activities shall be complete as soon as environmental conditions will permit.

Response: CA COMPLETED

Date of Completion: 08/08/2024

Operator
Comment:

Operator has addressed the weeds and undesirable vegetation and mowed around this location, and seeding will be scheduled when temperatures are ideal and moisture is consistent in order to comply with Rule 1004.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed:

Title: Sr Regulatory Analyst

Date: 8/12/2024 1:14:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403886155	FIR RESOLUTION SUBMITTED
403886201	Inspection Report Resolution

Total Attach: 2 Files