

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403886098

Date Received:

08/13/2024

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 51130

Name of Operator: LOCIN OIL CORPORATION

Address: 600 TRAVIS STREET SUITE 5050

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

Tyler Faldyn

832-748-1090

tfaldyn@americanhelium.us

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 696204915

Inspection Date: 05/08/2023

FIR Submit Date: 05/09/2023

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: LOCIN OIL CORPORATION

Company Number: 51130

Address: 600 TRAVIS ST STE 6161

City: HOUSTON State: TX Zip: 77002

**LOCATION - Location ID: 322403**

Location Name: FEDERAL-67S104W Number: 34NWNE County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 34 Twp: 7S Range: 104W Meridian: 6

Latitude: 39.412954 Longitude: -108.974062

**FACILITY - API Number: 05-045- -00 Facility ID: 322403**

Facility Name: FEDERAL-67S104W Number: 34NWNE

Qtrqtr: NWNE Sec: 34 Twp: 7S Range: 104W Meridian: 6

Latitude: 39.412954 Longitude: -108.974062

**CORRECTIVE ACTIONS:**

1 CA# 170707

Corrective Action: Install sign to comply with Rule 605.h.

Date: 05/03/2023

Response: CA COMPLETED

Date of Completion: 06/26/2023

Operator Comment: Locin responded to this corrective action on Document #696205061 on 06/26/2023. We are submitting this FIRR to close the record. Please see attached photo of signage.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 170708

Corrective Action: Comply with 1003.a

Date: 11/30/2022

Response: CA COMPLETED

Date of Completion: 06/26/2023

Operator Comment: Locin responded to this corrective action on Document #696205061 on 06/26/2023. We are submitting this FIRR to close the record.

ECMC Decision:

ECMC  
Representative:

3 CA# 170709

Corrective Action: Comply with 1002.f: Install or repair required stormwater and erosion control BMPs at access road to properly manage runoff.

Date: 04/07/2023

Response: CA COMPLETED

Date of Completion: 06/26/2023

Operator Comment: Locin responded to this corrective action, as documented on the inspection Document #696205061 on 06/26/2023. We are submitting this FIRR to close the record.

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Locin is submitting this FIRR to correct and resolve the historic records.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Niah Wilson

Signed:

Title: Regulatory Specialist

Date: 8/13/2024 1:43:06 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403886098	FIR RESOLUTION SUBMITTED
403886109	Field Inspection Form Response
403888071	Federal 1-34 Signage Photo
403888073	Federal 1-34 Tank Label

Total Attach: 4 Files