

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403890400

Date Received:

08/15/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Bongers, Brent

361-935-5633

bbongers@impetroresources.com

Kyle Waggoner

kyle.waggoner@state.co.us

Krystal Heibel

krystal.heibel@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100361

Inspection Date: 08/01/2024

FIR Submit Date: 08/06/2024

FIR Status: _____

Inspected Operator Information:

Company Name: IMPETRO RESOURCES LLC

Company Number: 10690

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

LOCATION - Location ID: 316957

Location Name: ANN ALLISON-63S54W

Number: 22NWNW

County: _____

Qtrqtr: NWN
W

Sec: 22

Twp: 3S

Range: 54W

Meridian: 6

Latitude: 39.781190

Longitude: -103.421610

FACILITY - API Number: 05-121- -00

Facility ID: 316957

Facility Name: ANN ALLISON-63S54W

Number: 22NWNW

Qtrqtr: NWN
W

Sec: 22

Twp: 3S

Range: 54W

Meridian: 6

Latitude: 39.781190

Longitude: -103.421610

CORRECTIVE ACTIONS:

1 CA# 197426

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 09/19/2024

Response: CA COMPLETED

Date of Completion: 08/08/2024

Per Rule 912.d.(1) berms around tanks and pits have been repaired. Photo log of repaired berms is attached.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 197427

Corrective Action: Properly dispose of oily waste in accordance with 905.e..

Date: 08/09/2024

Response: CA COMPLETED

Date of Completion: 08/09/2024

Operator
Comment:

Per Rule 905.e. oil stained soil at the treater has been removed and properly disposed of. Manifest is attached.

ECMC Decision:

ECMC
Representative:

3 CA# 197428

Corrective Action: Operator shall remediate the historic release by delineating horizontal and vertical extent of impacted area using the Table 915-1 Protection of Groundwater Soil Screening Level Concentrations and remediate impacts to Table 915-1 standards. Documentation must include a figure showing spill area with sample locations plus laboratory results. This informations shall be submitted within a Form 19 submittal.

Date: 08/09/2024

Response: CA COMPLETED

Date of Completion: 08/09/2024

Operator
Comment:

Historical spill impacts were addressed under the former Remediation Project #8309. The Remediation/Reclamation report is attached.

ECMC Decision:

ECMC
Representative:

4 CA# 197429

Corrective Action: Comply with Rule 606

Date: 08/13/2024

Response: CA COMPLETED

Date of Completion: 08/08/2024

Operator
Comment:

Per Rule 606, trash and debris around location has been cleaned up around location.

ECMC Decision:

ECMC
Representative:

5 CA# 197430

Corrective Action: Comply with Rule 606

Date: 11/06/2024

Response: CA COMPLETED

Date of Completion: 08/08/2024

Operator
Comment:

Per Rule 606, unused equipment has been removed from location.

ECMC Decision:

--

Date: 08/13/2024

Date of Completion: 08/12/2024

Operator sent an email per ECMC Staff, Krystal Heibel, request on 8/12/2024. Communication is attached. Ann Allison has an active Discharge Permit #COG840016. Site has not discharged since 20218.

Signed:

Date: 8/15/2024 12:42:52 PM

<u>Document Number</u>	<u>Description</u>
403890400	FIR RESOLUTION SUBMITTED
403890515	Photolog
403890516	Manifest
403890517	ECMC Communication
403890519	Remediation/Reclamation Report

Page 3 of 3