

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403948716

Date Received:
10/07/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Bongers, Brent

Phone

361-935-5633

Email

bbongers@impetroresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201604

Inspection Date: 09/10/2024

FIR Submit Date: 09/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: IMPETRO RESOURCES LLC

Company Number: 10690

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

LOCATION - Location ID: 317278

Location Name: CHANDLER-62N49W Number: 15NWNE County: _____

Qtrqtr: NWNE Sec: 15 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.145840 Longitude: -102.840590

FACILITY - API Number: 05-121- -00 Facility ID: 317278

Facility Name: CHANDLER-62N49W Number: 15NWNE

Qtrqtr: NWNE Sec: 15 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.145840 Longitude: -102.840590

CORRECTIVE ACTIONS:

1 CA# 198773

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 09/15/2024

Response: CA COMPLETED

Date of Completion: 10/01/2024

Operator Comment: Pit berms have been repaired and drainage ditches have been built around the berms to prevent sediment transport into adjacent areas.

ECMC Decision: _____

Date: 10/7/2024 5:37:28 PM

Page 2 of 2