

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403910962

Date Received:

09/05/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Price, Andrew

918-260-8324

aprice@arkomaops.com

General

SJBcompliance@arkomaops.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000889

Inspection Date: 06/25/2024

FIR Submit Date: 07/01/2024

FIR Status: _____

Inspected Operator Information:

Company Name: ARKOMA OPERATIONS LLC

Company Number: 10766

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 333602

Location Name: OLSON-SMITH UNIT-N33N8W Number: 8SESE County: _____

Qtrqtr: SESE Sec: 8 Twp: 33N Range: 8W Meridian: N

Latitude: 37.114019 Longitude: -107.735344

FACILITY - API Number: 05-067- -00 Facility ID: 333602

Facility Name: OLSON-SMITH UNIT-N33N8W Number: 8SESE

Qtrqtr: SESE Sec: 8 Twp: 33N Range: 8W Meridian: N

Latitude: 37.114019 Longitude: -107.735344

CORRECTIVE ACTIONS:

1 CA# 196332

Corrective Action: Comply with rule 1004.e

Date: 07/08/2024

Response: CA COMPLETED

Date of Completion: 09/02/2024

Operator
Comment:

Arkoma Operating worked with Red Cedar Gathering Company and Red Willow Production Company to have their abandoned and unused piping and equipment removed from the disturbance area. Once this was done a contractor working for Arkoma Operating, re-contoured, seeded and mulched the disturbance area with a seed mixture recommended by the local County NRCS office. Erosion BMP's were used to stabilize the re-seeded soil and will continue to be monitored until Rule 1004 standards are met.

ECMC Decision: _____

ECMC
Representative: _____

2 CA# 196333

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: _____

No CA date is being provided as this location is out of compliance for the same Rule identified in the previous inspection doc #714000107.

Response: CA COMPLETED _____

Date of Completion: 09/02/2024 _____

Operator Comment: Arkoma Operating worked with Red Cedar Gathering Company and Red Willow Production Company to have their abandoned and unused piping and equipment removed from the disturbance area. Once this was done a contractor working for Arkoma Operating, re-contoured, seeded and mulched the disturbance area with a seed mixture recommended by the local County NRCS office. Erosion BMP's were used to stabilize the re-seeded soil and will continue to be monitored until Rule 1004 standards are met.

ECMC Decision: _____

ECMC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh _____

Signed: _____

Title: Engineering Analyst _____

Date: 9/5/2024 12:39:11 PM _____

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403910962	FIR RESOLUTION SUBMITTED
403910973	Remedial report with photos

Total Attach: 2 Files