

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403912453

Date Received:
09/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10773
Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC
Address: 5251 DTC PKWY STE 950
City: GREENWOOD VILLAGE State: CO Zip: 80111

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|------------------|--------------|-------------------------------|
| Parrish, Melissa | 970-397-3896 | mparrish@fundareresources.com |
| Smith, Sydney | 303-910-4511 | ssmith@fundareresources.com |

ECMC INSPECTION SUMMARY:

FIR Document Number: 708200653
Inspection Date: 10/26/2023 FIR Submit Date: 10/31/2023 FIR Status:

Inspected Operator Information:

Company Name: FUNDARE RESOURCES OPERATING COMPANY LLC Company Number: 10773
Address: 5251 DTC PKWY STE 950
City: GREENWOOD VILLAGE State: CO Zip: 80111

LOCATION - Location ID: 445579

Location Name: Horsetail Number: 30H Pad County:
Qtrqr: SENE Sec: 30 Twp: 10N Range: 57W Meridian: 6
Latitude: 40.810644 Longitude: -103.787250

FACILITY - API Number: 05-123-00 Facility ID: 445579

Facility Name: Horsetail Number: 30H Pad
Qtrqr: SENE Sec: 30 Twp: 10N Range: 57W Meridian: 6
Latitude: 40.810644 Longitude: -103.787250

CORRECTIVE ACTIONS:

1 CA# 187459

Corrective Action: Comply with Rule 606. The location will remain out of compliance until the corrective action has been completed.

Date: 10/26/2023

Response: CA COMPLETED

Date of Completion: 01/15/2024

Operator Comment: Jersey barriers are no longer being stored on location. These jersey barriers have been implemented around wellheads to create visible barrier putting site within compliance of Rule 606. - Please see attached photo documentation.

ECMC Decision: _____

ECMC
Representative:

2 CA# 187460

Corrective Action: Comply with Rule 606. The location will remain out of compliance until the corrective action has been completed.

Date: 10/26/2023

Response: CA COMPLETED

Date of Completion: 01/15/2024

Operator
Comment:

All trash & debris including the flare foundation have been removed & properly disposed of from location in compliance with Rule 606. Please see attached photo documentation.

ECMC Decision: _____

ECMC
Representative:

3 CA# 187461

Corrective Action: Comply with Rule 1003. The locaiton will remain out of compliance until the corrective action has been resolved.

Date: 10/26/2023

Response: CA COMPLETED

Date of Completion: 09/06/2024

Operator
Comment:

Photos obtained during this inspection occurred during the dormant season. In compliance with Rule 1003, you can see in the provided photo documentation from the Vegetation Assessment performed by Marcom the Drill Pad Post Reclamation Vegetation has surpassed the reference area with native grass.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Melissa Parrish

Signed: _____

Title: Production Compliance Reg

Date: 9/6/2024 1:10:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| Document Number | Description |
|------------------------|--|
| 403912453 | FIR RESOLUTION SUBMITTED |
| 403912471 | Horsetail 30 H Pad COGCC Corrective Actions Completed |
| 403912472 | Horsetail 30H - Vegetation Assessment Photo doc 9.4.2024 |

Total Attach: 3 Files