

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2024

Submitted Date:

10/11/2024

Document Number:

717900059

**FIELD INSPECTION FORM**

Loc ID: 323453    Inspector Name: Robinson, Taylor    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER    State: CO    Zip: 80217-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>
Chris Binschus		chris.binschus@state.co.us	

**General Comment:**

This is an environmental inspection for Facility ID 245261 Halverson 1 TB and WH. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions. LO was onsite during inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: [Statewide unnecessary equipment, weeds, waste, and trash requirements](#)

Corrective Action: [Comply with Rule 606](#)

Date: 10/26/2024

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

[This inspection was in response to a spill at this location from November 2023, with ongoing remediation. Groundwater monitoring wells have been implemented at the wellhead and are planned for the tank battery. Ideally the Operator will construct the wells at the tank battery prior to December 1, 2024 due to an active bald eagle nest within close proximity to the excavation area, which would deter work until after August 1, 2025.](#)

Multiple Spills and Releases?

**Fencing/:**

Type

Comment: [There is cattle guard fencing currently surrounding the large open excavation. It appears to be functioning properly.](#)

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Location Construction**

Location ID: 245261 CDP: \_\_\_\_\_

Comment: There is currently an open excavation at this location which is approximately 40ft long by 20ft wide by 15 ft deep. It is surrounded by cattle guard.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: ECMC environmental and reclamation staff have been on location and are tracking clean up operations. The Operator has delineated soil impacts vertically but are still trying to fully delineate to the East. The Operator has stated these activities will continue next week and will be completed prior to the bald eagle stipulation coming into effect. Additionally, the Operator plans to install monitoring wells at the TB prior to the eagle stip.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
Remediation activities are ongoing at this location. The LO is not happy with the situation as it has been going on for several years with no tangible results toward completion. The LO is also very concerned that the Operator is unable or unwilling to provide the proper top soil for his crops upon completion of the remediation.	robinsotl	10/11/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403954810	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743120">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743120</a>
717900060	photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743118">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743118</a>