

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403964924

Date Received:
10/21/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Heil, John</u>		<u>john.heil@state.co.us</u>
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708904806
Inspection Date: 10/14/2024 FIR Submit Date: 10/14/2024 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 432398

Location Name: Savage Number: RWF 23-25 County: _____
Qtrqtr: NESW Sec: 25 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.493826 Longitude: -107.837844

FACILITY - API Number: 05-045-00 Facility ID: 432398

Facility Name: Savage Number: RWF 23-25
Qtrqtr: NESW Sec: 25 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.493826 Longitude: -107.837844

CORRECTIVE ACTIONS:

1 CA# 199667

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition. Date: 10/15/2024

Response: CA COMPLETED Date of Completion: 10/14/2024

Operator Comment: A voicemail message was received from Inspector Smelser at 1:21 p.m. on 10/14/24 informing TEP of a leaking chemical containment tank located at the RWF 23-25-694 well pad. This information was immediately relayed to the Production Field Supervisor, Chuck Smith. Production personnel were in close proximity to the pad at the time of the notification and responded to the potential leak within minutes. Upon investigation, it was discovered that a loose pump fitting was causing a slow drip of fluid (corrosion inhibitor) to run down the injection line and

over the lip of the containment structure. The fitting was immediately tightened and the leak was stopped. Fluids that collected in the containment structure were evacuated, and the small volume of stained soils off the NE corner of the containment were also cleaned up on the same day (10/14/24). M. Gardner (TEP) spoke with W. Smelser (ECMC) on 10/14/24 and confirmed that the leak had been addressed. See attached photo.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: A voicemail message was received from Inspector Smelser at 1:21 p.m. on 10/14/24 informing TEP of a leaking chemical containment tank located at the RWF 23-25-694 well pad. This information was immediately relayed to the Production Field Supervisor, Chuck Smith. Production personnel were in close proximity to the pad at the time of the notification and responded to the potential leak within minutes. Upon investigation, it was discovered that a loose pump fitting was causing a slow drip of fluid (corrosion inhibitor) to run down the injection line and over the lip of the containment structure. The fitting was immediately tightened and the leak was stopped. Fluids that collected in the containment structure were evacuated, and the small volume of stained soils off the NE corner of the containment were also cleaned up on the same day (10/14/24). M. Gardner (TEP) spoke with W. Smelser (ECMC) on 10/14/24 and confirmed that the leak had been addressed. See attached photo.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 10/21/2024 4:12:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403965027	Photo of chemical containment and soils
-----------	-----------------------------------------

Total Attach: 1 Files