

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403965363

Date Received:
10/22/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 7650

Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION

Address: 4900 COLLEGE BLVD

City: FARMINGTON State: NM Zip: 87402

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Stradling, Zach

zstradling@bmgsdrilling.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001350

Inspection Date: 10/15/2024

FIR Submit Date: 10/17/2024

FIR Status: _____

Inspected Operator Information:

Company Name: BENSON-MONTIN-GREER DRILLING CORPORATION

Company Number: 7650

Address: 4900 COLLEGE BLVD

City: FARMINGTON State: NM Zip: 87402

LOCATION - Location ID: 428734

Location Name: JACQUES 2-10-N33-10W Number: _____ County: _____

Qtrqr: SENE Sec: 4 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135284 Longitude: -107.934125

FACILITY - API Number: 05-067- -00 Facility ID: 428734

Facility Name: JACQUES 2-10-N33-10W Number: _____

Qtrqr: SENE Sec: 4 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135284 Longitude: -107.934125

CORRECTIVE ACTIONS:

1 CA# 199840

Corrective Action: Comply with rule 1004, reclaim access point of location.

Date: 11/01/2024

Response: CA COMPLETED

Date of Completion: 10/21/2024

Operator Comment: Access has not been fully reclaimed to allow for rework to be completed as necessary. Access will be recontoured and decompacted once the slope and pad are stabilized.

ECMC Decision: _____

ECMC Representative:			
2	CA# 199841		
Corrective Action:	Comply with rule 1002f. Install or repair required BMPs.		Date: <u>10/24/2024</u>
Response:	CA COMPLETED	Date of Completion: <u>10/21/2024</u>	
Operator Comment:	New erosion logs have been installed to repair the rill. The sediment deposition behind the erosion log has been removed to allow the BMP to function.		
ECMC Decision:			
ECMC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>Zach Stradling</u>	Signed: _____
Title: <u>Vice President</u>	Date: <u>10/22/2024 9:10:57 AM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403965436	BMP Repair Pic
403965438	BMP Repair Pic
403965439	BMP Repair Pic

Total Attach: 3 Files