

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403966710

Date Received:
10/22/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Longworth, Mike</u>		<u>michael.longworth@state.co.us</u>
<u>Bechtolt, Phoebe</u>		<u>pbechtolt@maralexinc.com</u>
<u>O'Hare, Mollie</u>		<u>mollieo@maralexinc.com</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 700300752

Inspection Date: 10/01/2024 FIR Submit Date: 10/03/2024 FIR Status: _____

Inspected Operator Information:

Company Name: MARALEX RESOURCES INC Company Number: 53255

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

LOCATION - Location ID: 333566

Location Name: SHELHAMMER-N33N7W Number: 10NWSW County: _____

Qtrqtr: NWS Sec: 10 Twp: 33N Range: 7W Meridian: N

Latitude: 37.115320 Longitude: -107.601250

FACILITY - API Number: 05-067-00 Facility ID: 333566

Facility Name: SHELHAMMER-N33N7W Number: 10NWSW

Qtrqtr: NWS Sec: 10 Twp: 33N Range: 7W Meridian: N

Latitude: 37.115320 Longitude: -107.601250

CORRECTIVE ACTIONS:

1 CA# 199262

Corrective Action: Comply with Rules 912 and 913.c

Date: 10/04/2024

Response: CA COMPLETED

Date of Completion: 10/22/2024

Operator Comment: Due to inclement weather and shortage of staff we are delayed on this project, but we plan to resume work on this location the first week of November and plan to submit an updated FIRR with photos that following week.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 199263

Corrective Action: Comply with all 900, 1000 and 1100 series rules. Immediately remove fluid from buried vessel and fluid filled spill prevention device. Remove all equipment, tanks, junk, trash and debris. Comply with any existing Form 27 COAs, File new and update existing spill reports and remediation plans. Follow up with environmental and integrity staff. Abandon flowlines. Clean up facility to comply with table 915-1 standards. Reclaim production area of PA well and facility 429650 and tank battery 4777716.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/22/2024

Operator Comment: Due to inclement weather and shortage of staff we are delayed on this project, but we plan to resume work on this location the first week of November and plan to submit an updated FIRR with photos that following week.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Due to inclement weather and shortage of staff we are delayed on this project, but we plan to resume work on this location the first week of November and plan to submit an updated FIRR with photos that following week.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mollie O'Hare

Signed: _____

Title: E.A.

Date: 10/22/2024 7:46:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403966710	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files