

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403878809

Date Received:
10/24/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708300751

Inspection Date: 08/08/2023

FIR Submit Date: 08/11/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334818

Location Name: FEDERAL-67S96W Number: 3NWNW County: GARFIELD

Qtrqtr: NWN Sec: 3 Twp: 7S Range: 96W Meridian: 6
W

Latitude: 39.471824 Longitude: -108.099789

FACILITY - API Number: 05-045-00 Facility ID: 211044

Facility Name: FEDERAL Number: GR 21-3 V

Qtrqtr: NWN Sec: 3 Twp: 7S Range: 96W Meridian: 6
W

Latitude: 39.471824 Longitude: -108.099789

CORRECTIVE ACTIONS:

1 CA# 178176

Corrective Action: Install liner material to ensure spill or released materials will be maintained with containment structure to comply with Rule 603.o.

Date: 09/10/2023

Response: CA COMPLETED

Date of Completion: 08/15/2023

Operator
Comment:

Liner is effective and in good condition. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

2 CA# 178177

Corrective Action: Install/correct label to comply with Rule 605.h.

Date: 09/10/2023

Response: CA COMPLETED

Date of Completion: 08/15/2023

Operator
Comment:

Methanol tank is now labeled with capacity. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

3 CA# 178178

Corrective Action: Secure separator to comply with Rule 608.

Date: 08/26/2023

Response: CA COMPLETED

Date of Completion: 08/15/2023

Operator
Comment:

Separator hatch is now closed to prevent wildlife entry. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

4 CA# 178179

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 08/26/2023

Response: CA COMPLETED

Date of Completion: 09/19/2023

Operator
Comment:

Location and access road has been bladed/graded to remove rutting and rills. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #178176: Liner is effective and in good condition. Corrective Action complete.
CA #178177: Methanol tank is now labeled with capacity. Corrective Action complete.
CA #178178: Separator hatch is now closed to prevent wildlife entry. Corrective Action complete.
CA #178179: Location and access road have been bladed/graded to remove erosion. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 10/24/2024 2:09:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403878809	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files