

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403969718

Date Received:

10/24/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Javernick, James

javernick1@gmail.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 690203639

Inspection Date: 12/01/2022

FIR Submit Date: 12/05/2022

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: JAVERNICK OIL

Company Number: 44390

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

### LOCATION - Location ID: 322227

Location Name: SLANOVICH-619S69W Number: 32NWSW County: FREMONT

Qtrqtr: NWS Sec: 32 Twp: 19S Range: 69W Meridian: 6  
W

Latitude: 38.350170 Longitude: -105.140940

### FACILITY - API Number: 05-043-00 Facility ID: 210044

Facility Name: SLANOVICH Number: 32-1

Qtrqtr: NWS Sec: 32 Twp: 19S Range: 69W Meridian: 6  
W

Latitude: 38.350170 Longitude: -105.140940

### CORRECTIVE ACTIONS:

1 CA# 166371

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.

Date: 11/11/2022

Response: CA COMPLETED

Date of Completion: 09/10/2024

Operator  
Comment:

Crew removed the contaminated soil replaced the soil with clean surrounding dirt. Tank has been removed. See photos in Attachments Tab.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 166372

Corrective Action: Install sign to comply with Rule 605.c.

Date: 12/08/2022

Response: CA COMPLETED

Date of Completion: 04/22/2023

Operator  
Comment: Inspection conducted May 22, 2023 (Document #690203824) observed that drilling operations had ended and the rig was released from location. d

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 166373

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/30/2022

Response: CA COMPLETED

Date of Completion: 10/14/2024

Operator  
Comment: Interim Reclamation has commenced and berms have been built up around the location.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 10/24/2024 4:12:09 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403969718	FIR RESOLUTION SUBMITTED
403969793	Location Photos

Total Attach: 2 Files