

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403969813

Date Received:

10/24/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Javernick, James

javernick1@gmail.com

Javernick, Salene

salenej@gmail.com

Beardslee, Tom

tom.beardslee@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 690203824

Inspection Date: 01/24/2023

FIR Submit Date: 01/25/2023

FIR Status: _____

Inspected Operator Information:

Company Name: JAVERNICK OIL

Company Number: 44390

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

LOCATION - Location ID: 322227

Location Name: SLANOVICH-619S69W Number: 32NWSW County: FREMONT

Qtrqr: NWS Sec: 32 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.350170 Longitude: -105.140940

FACILITY - API Number: 05-043-00 Facility ID: 210044

Facility Name: SLANOVICH Number: 32-1

Qtrqr: NWS Sec: 32 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.350170 Longitude: -105.140940

CORRECTIVE ACTIONS:

1 CA# 167156

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.
Conduct maintenance on equipment, clean up stained material and review self inspection processes.

Date: 11/11/2022

Response: CA COMPLETED

Date of Completion: 09/01/2024

Operator Comment: Contaminated soils have been removed and properly disposed of. Tank has been removed. See photos in Attachments Tab.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 167157

Corrective Action: Immediately clean up. Implement or modify BMPs for improved material handling and spill prevention. Properly dispose of empty containers.

Date: 01/24/2023

Response: CA COMPLETED

Date of Completion: 09/26/2024

Operator Comment: Equipment has been removed from location and cleaned up spills have been cleaned up.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 167158

Corrective Action: Implement BMP following good engineering practices.

Date: 01/26/2023

Response: CA COMPLETED

Date of Completion: 03/31/2023

Operator Comment: Inspection (Document #690204043) conducted on 3/31/2023 does not indicate that the portable outhouse needed to be staked down. Since then, all unused equipment has been removed from location.

ECMC Decision: _____

ECMC Representative: _____

4 CA# 167159

Corrective Action: Install sign to comply with Rule 605.c.

Date: 12/08/2022

Response: CA COMPLETED

Date of Completion: 04/22/2023

Operator Comment: Inspection conducted May 22, 2023 (Document #690203824) observed that drilling operations had ended and the rig was released from location.

ECMC Decision: _____

ECMC Representative: _____

5 CA# 167160

Corrective Action: Comply with 905.g.
Immediately clean up. Implement or modify BMPs for improved material handling and spill prevention.

Date: 01/24/2023

Response: CA COMPLETED

Date of Completion: 09/16/2024

Operator Comment: Drill cuttings have been removed location.

ECMC Decision: _____

Interim Reclamation has commenced and berms have been built up around the location.

--

Date: 10/24/2024 4:51:09 PM

<u>Document Number</u>	<u>Description</u>
403969813	FIR RESOLUTION SUBMITTED
403969901	Location Photos

Page 3 of 3