

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403970058

Date Received:
10/25/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Javernick, Salene

salenej@gmail.com

Beardslee, Tom

tom.beardslee@state.co.us

Javernick, James

javernick1@gmail.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 690204043

Inspection Date: 03/31/2023

FIR Submit Date: 04/03/2023

FIR Status: _____

Inspected Operator Information:

Company Name: JAVERNICK OIL

Company Number: 44390

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

LOCATION - Location ID: 322227

Location Name: SLANOVICH-619S69W Number: 32NWSW County: FREMONT

Qtrqtr: NWS Sec: 32 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.350170 Longitude: -105.140940

FACILITY - API Number: 05-043-00 Facility ID: 210044

Facility Name: SLANOVICH Number: 32-1

Qtrqtr: NWS Sec: 32 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.350170 Longitude: -105.140940

CORRECTIVE ACTIONS:

1 CA# 168856

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 11/11/2022

Response: CA COMPLETED

Date of Completion: 09/10/2024

Contaminated soils have been removed and properly disposed of. Tank has been removed. See attached photos

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 168857

Corrective Action: Install sign to comply with Rule 605.c.

Date: 12/08/2022

Response: CA COMPLETED

Date of Completion: 04/22/2023

Operator
Comment:

Inspection conducted May 22, 2023 (Document #690203824) observed that drilling operations had ended and the rig was released from location.

ECMC Decision:

ECMC
Representative:

3 CA# 168858

Corrective Action: Immediately clean up. Implement or modify BMPs for improved material handling and spill prevention. Properly dispose of empty containers.

Date: 01/24/2023

Response: CA COMPLETED

Date of Completion: 09/26/2024

Operator
Comment:

Equipment has been removed from location and cleaned up spills have been cleaned up.

ECMC Decision:

ECMC
Representative:

4 CA# 168859

Corrective Action: Comply with 905.g. Immediately clean up. Implement or modify BMPs for improved material handling and spill prevention.

Date: 01/24/2023

Response: CA COMPLETED

Date of Completion: 09/16/2024

Operator
Comment:

Drill cuttings have been removed location and properly disposed of

ECMC Decision:

ECMC
Representative:

5 CA# 168860

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/30/2022

Response: CA COMPLETED

Date of Completion: 10/14/2024

Operator
Comment:

Interim Reclamation has commenced and berms have been built up around the location.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed:

Title: Compliance Specialist

Date: 10/25/2024 8:13:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403970058	FIR RESOLUTION SUBMITTED
403970109	Location Photos
403970112	Waste Manifest

Total Attach: 3 Files