

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403879783

Date Received:
10/28/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708901191
Inspection Date: 07/31/2023 FIR Submit Date: 07/31/2023 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 336015

Location Name: ROBINSON-66S92W Number: 8SWSW County: _____
Qtrqtr: SWS Sec: 8 Twp: 6S Range: 92W Meridian: 6
W
Latitude: 39.535817 Longitude: -107.699357

FACILITY - API Number: 05-045-00 Facility ID: 336015

Facility Name: ROBINSON-66S92W Number: 8SWSW
Qtrqtr: SWS Sec: 8 Twp: 6S Range: 92W Meridian: 6
W
Latitude: 39.535817 Longitude: -107.699357

CORRECTIVE ACTIONS:

1 CA# 176880

Corrective Action: The storage of equipment not necessary for use on location is prohibited. Date: 06/30/2023

Response: CA COMPLETED Date of Completion: 08/03/2023

Operator Comment: Equipment has been removed from the secondary containment. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

3 CA# 176882

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 06/30/2023

Response: CA COMPLETED

Date of Completion: 08/07/2023

Operator Comment: Berm behind tank battery has been repaired. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #176880: Equipment has been removed from the secondary containment. Corrective Action complete.
CA #176881: Deadman anchor has been removed. Corrective Action Completed. Submitted on 4/9/2024 document #403747579.
CA #176882: Berm behind tank battery has been repaired. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 10/28/2024 10:52:48 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403879783	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files