

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2024

Submitted Date:

10/28/2024

Document Number:

713601572

FIELD INSPECTION FORM

Loc ID 478057 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	
B WARD, GIENA		gward@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478058	TANK BATTERY	AC	09/17/2020		-	A.C. Tank Battery	RI

General Comment:

This is a follow up of the previous reclamation inspections: #713601248, #713601444.
The corrective actions of the previous inspections have not been completed.
Operator is directed to perform all outstanding corrective actions immediately.

Location

Overall Good:

Signs/Marker:

Type	BATTERY			
Comment:	There is no sign posted at the tank battery.			
Corrective Action:	Install sign to comply with Rule 605.e.		Date:	10/17/2024

Emergency Contact Number:

Comment:				
Corrective Action:			Date:	_____

Good Housekeeping:

Type	OTHER			
Comment:	There is inadequate netting covering the open top tank to prevent wildlife entry. There is a secondary containment which was full of oily fluids with no netting. Previous CA was not completed.			
Corrective Action:	Install or repair wildlife protection equipment. Comply with rule 902.b.		Date:	07/31/2024

Overall Good:

Spills:

Type	Area	Volume		
	Truck Loadout			
Comment:	There are oil stained soils in front of the west tank battery which have not been cleaned up. Previous CA was not completed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a		Date:	08/26/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No				
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are still signs of sediment and vehicle tracking onto the road that need to be cleaned up and controlled with BMP's. The check dams installed have filled in with sediment and need to be cleaned out. Additional BMPs need to be installed to prevent continued erosion along the roadside.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 10/08/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601573	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6763986