

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403882542

Date Received:
10/30/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Byers, Jim</u>		<u>jbyers@blm.gov</u>
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708901019
Inspection Date: 07/13/2023 FIR Submit Date: 07/13/2023 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335368

Location Name: FEDERAL-66S94W Number: 19NWSE County:
Qtrqtr: NWSE Sec: 19 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.507259 Longitude: -107.928991

FACILITY - API Number: 05-045-00 Facility ID: 335368

Facility Name: FEDERAL-66S94W Number: 19NWSE
Qtrqtr: NWSE Sec: 19 Twp: 6S Range: 94W Meridian: 6
Latitude: 39.507259 Longitude: -107.928991

CORRECTIVE ACTIONS:

1 CA# 175413

Corrective Action: All load lines will be capped or plugged Date: 07/20/2023

Response: CA COMPLETED Date of Completion: 07/17/2023

Operator Comment: Bull plug was installed on open ended load line. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

2 CA# 175414

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 07/27/2023

Response: CA COMPLETED

Date of Completion: 07/17/2023

Operator
Comment:

The 2 deadman have been marked. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #175413: Bull plug was installed on open ended load line. Corrective Action complete.
CA #175414: The 2 deadman have been marked. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 10/30/2024 1:06:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files