

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2024

Submitted Date:

11/01/2024

Document Number:

711901338**FIELD INSPECTION FORM**Loc ID 312211 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 88370Name of Operator: TIMKA RESOURCES LTDAddress: 2077 BAYFRONT DRCity: WINDSOR State: CO Zip: 80550**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pivonka, Todd		pivonka2010@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219558	WELL	PR	02/28/2011	OW	075-06510	KIRK-LYNCH 1	PR

General Comment:

SNAP SHOT FIR 2024 SATISFACTORY

Location				
Lease Road:				
Type	Access			
comment:	MAINTAIN LEASE ROAD			
Corrective ActionL				Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	SATISFACTORY			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	SATISFACTORY			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	NONE			
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Other	# 0			corrective date
Comment:	NO CHANGE			
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	219558	Type:	WELL	API Number:	075-06510	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	OW								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

ECMC Comments		
Comment	User	Date
SNAP SHOT FIR 2024 SATISFACTORY	schureky	11/01/2024