

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403979943

Date Received:
11/01/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

alex.fischer@state.co.us

scott.ramsey@state.co.us

kris.neidel@state.co.us

rikki.ross@fulcrumeo.com

wes.corliss@fulcrumeo.com

inspections@fulcrumeo.com

annalee@fulcrumef.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 697505283

Inspection Date: 04/15/2024

FIR Submit Date: 05/17/2024

FIR Status: _____

Inspected Operator Information:

Company Name: FULCRUM ENERGY OPERATING LLC

Company Number: 10805

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

LOCATION - Location ID: 467526

Location Name: Spicer S32 Number: Annex Pad County: _____

Qtrqtr: SWS Sec: 32 Twp: 7N Range: 80W Meridian: 6
W

Latitude: 40.529551 Longitude: -106.403819

FACILITY - API Number: 05-057- -00 Facility ID: 467526

Facility Name: Spicer S32 Number: Annex Pad

Qtrqtr: SWS Sec: 32 Twp: 7N Range: 80W Meridian: 6
W

Latitude: 40.529551 Longitude: -106.403819

CORRECTIVE ACTIONS:

Corrective Action: Comply with Rule 1003.b. to reduce all areas not needed for production operations. All areas compacted by drilling and subsequent oil and gas operations which are no longer needed shall be cross-ripped to a depth of eighteen (18) inches. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/25/2024

Operator Comment: Site area has been reduced. Site has been reseeded and mulched. Erosion blanket has been installed on topsoil stockpile. Fulcrum has implemented a weed-spraying program. Site will be sprayed in spring of 2025, following snowmelt. The site will then be re-evaluated for additional spraying as the year progresses.

ECMC Decision: _____

ECMC
Representative:**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed: _____

Title: EHS Field Advisor

Date: 11/1/2024 4:33:47 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403979943	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files