

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403988717

Date Received:
11/08/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Lacey Granillo	5057870118	lgranillo@logosresourcesllc.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001414
Inspection Date: 10/28/2024 FIR Submit Date: 10/31/2024 FIR Status:

Inspected Operator Information:

Company Name: SIMCOE LLC Company Number: 10749
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 333627

Location Name: COLORADO 32-7-N32N7W Number: 3SWNE County:
Qtrqtr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N
Latitude: 37.049260 Longitude: -107.592280

FACILITY - API Number: 05-067- -00 Facility ID: 333627

Facility Name: COLORADO 32-7-N32N7W Number: 3SWNE
Qtrqtr: SWNE Sec: 3 Twp: 32N Range: 7W Meridian: N
Latitude: 37.049260 Longitude: -107.592280

CORRECTIVE ACTIONS:

1 CA# 200190

Corrective Action: Comply with rule 606. Remove and properly store unused equipment. Date: 11/15/2024

Response: CA COMPLETED Date of Completion: 11/08/2024

Operator Comment: in process this is not complete

ECMC Decision:

ECMC
Representative:

2 CA# 200191

Corrective Action: Comply with rule 606. Remove surface owner equipment.

Date: 11/30/2024

Response: CA COMPLETED

Date of Completion: 11/08/2024

Operator Comment: in process this is not complete

ECMC Decision:

ECMC
Representative:

3 CA# 200192

Corrective Action: Comply with rule 1002f. Install or repair required BMPs.

Date: 11/08/2024

Response: CA COMPLETED

Date of Completion: 11/08/2024

Operator Comment: LOGOS has repaired the erosion and failing stormwater BMPs observed in the eastern interim reclamation area.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: LOGOS has repaired the erosion and failing stormwater BMPs observed in the eastern interim reclamation area.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lacey Granillo

Signed:

Title: Regulatory Specialist

Date: 11/8/2024 3:45:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403988717	FIR RESOLUTION SUBMITTED
403988734	Erosion Colorado 32-7 11
403988738	Erosion Colorado 32-7 11
403988739	Erosion Colorado 32-7 11
403988740	Erosion Colorado 32-7 11
403988741	Erosion Colorado 32-7 11

Total Attach: 6 Files